

THE PORT AUTHORITY of NY & NJMemorandum

To: Nelson Chanfrau  
From: David Warren  
Date: December 27, 1994  
Subject: WTC - Fire Incident of 12/23/94  
Ref:

Copy To: G. Cummiskey, F. Dalton, R. Earle

As requested, Frank Dalton investigated the fire incident at 2 WTC that occurred on December 23, 1994. The fire was located on the outside stairway between 2 WTC and the VISTA Hotel, down at the Liberty Street level. It was originally reported as a rubbish fire, but after further investigation, containers of flammable liquid were uncovered at the scene. The fire department labeled the fire to be of suspicious origin.

The fire was first detected by a duct smoke detector in air handling unit ACR 712 and area smoke detector CS 713 in the 7th floor MER at 2115 hours. FDNY was notified immediately. The fire was officially extinguished at 2145 hours, at which time FDNY ordered that the building's smoke purge system be activated. The amount of smoke infiltrating the building is not known but an unusual odor in the mezzanine area was still noticeable today.

Since the area has been cleaned, we do not have any information regarding the source of fuel involved in the incident. The fire was severe enough to ignite the exterior aluminum skin and involve wooden framing behind it. The fire was prevented from further progress due to insulation and firestopping.

I am waiting to receive a copy of the PA Police Fire Incident Report. A report will be available from FDNY in 10 to 12 days.



David Warren  
Senior Fire Protection Engineer  
Risk Management

THE PORT AUTHORITY OF NY & NJ

MEMORANDUM

TO: Nelson Chanfrau  
FROM: Max deVries/Frank Dalton  
DATE: March 30, 1994  
SUBJECT: ACTUAL 88, 56A CAR, 46TH FLOOR  
  
COPY TO: G. Cummiskey, R. Earle, D✓Warren

An actual 88 occurred in an elevator in "A" Tower at 10:24 a.m., Wednesday, March 30, 1994.

Car 56A was out of service for maintenance on the 46th floor. The source of the fire was rubbish inside the service panel in the elevator. The source of ignition was sparks from a grinding operation around the panel.

The first alarm was an odor of smoke on the 60th floor at 10:10 a.m. At 10:24 a.m., an actual 88 was announced for the 46th floor, "A" Tower. Smoke detectors were activated on the 46th floor for freight elevator and passenger elevator No. 17 and No. 49, and on the 44th floor freight elevator No. 50. A second alarm was transmitted at 10:29 a.m.

After arrival of the FDNY, smoke purge on floors 44 through 48 was ordered by Deputy Chief Myers at 10:30 a.m. The FDNY extinguished the fire with dry chemical extinguishers. Note that the extinguisher at the work site was empty. The condition was secured by 11:22 a.m.

We will keep you informed as more information becomes available.

Max deVries *Max deVries*  
Fire Protection Engineer  
Risk Management Division

THE PORT AUTHORITY OF NY & NJ

Memorandum

TO: Nelson Chanfrau  
FROM: David Warren  
DATE: May 23, 1996  
SUBJECT: WTC - CONCOURSE LEVEL - FINE & SHAPIRO RESTAURANT

COPY TO: G. Cumiskey, E. Petrick

At 1958 hours on May 21, 1996, a telephone call to the PAPD Emergency Desk identified an odor of smoke in the Fine and Shapiro Restaurant. At 2000 hours, a smoke detector alarm from device #2723 was received at the 5WTC Fire Command Station. A smoke condition was also noted in the kitchen area by the Manager of Fine and Shapiro Restaurant.

FDNY responded at 2005 hours. The fire was located in the HVAC control panel located in the utility room adjacent to the kitchen. Acting Battalion Chief, Bill Youngson, had the main power shut down to the panel which extinguished the fire. No other means of extinguishment was used.

The fire was limited to the confines of the HVAC control panel enclosure. This panel is used to control the HVAC and kitchen hood systems. The damage from the fire begins on the face of the panel where the keypad used to program the system is located. Wiring within the panel was damaged by the burning plastic. An examination of the electrical closet, the damaged HVAC control panel, and its components was performed by the Fire Protection Staff on May 22 at 0900 hours.

The fire appears to have originated in the control unit itself at the keypad. An increased amount of molten metal in the keypad and circuit board of the controller unit indicates this area as the point of origin. There was no damage beyond the panel itself.

While performing the investigation the manager of the restaurant, Bob Band, reported to Fire Protection staff that they were experiencing problems with the HVAC unit prior to the fire incident. At approximately 1700 hours that day, Bob was advised by his HVAC contractor that no one was available to check out the system. Bob was directed via telephone by the HVAC contractor on how to reprogram the panel to re-start the HVAC system. After attempting to re-start the system for 45 minutes, there were no positive results. The HVAC contractor arrived at 1915 hours and adjusted the system. Shortly after, Bob noticed a slight odor of smoke. Tiles in the kitchen were removed to trace the origin of the odor of smoke. It was then noted that the smoke was coming from the utility closet.

FDNY initially suspected that the fire was of suspicious origin. A FDNY Fire Marshall responded at 2235 hours and determined that the ignition of wood located on the floor below the panel was caused by molten plastic from the inside controller unit.

As a result of this incident, the solenoid valve controlling the cooking gas supply was shut down. A fire watch was instituted and the restaurant was re-opened for business on May 22 with the provisions that no cooking was allowed. Fire Protection staff have also witnessed a re-test of the

area smoke detector which incorrectly identified a fire alarm condition as a trouble signal.

The HVAC contractor has started repair work on the system. Plans have been proposed to shut down the restaurant on Friday, May 24 and complete all repairs to re-open the restaurant on Tuesday, May 28. At that time, Fire Protection staff will re-inspect and test the systems.

I will provide you with further information as it becomes available.

A handwritten signature in dark ink, appearing to read "D. Warren", is positioned above the typed name.

David Warren, Supervisor  
Fire Protection  
Risk Management

/am  
Attachment